



PPP

Part Number

DSI 9387-011

Description

Toe Ring Hole Repair
Kit

Box Part Number

Dimension

Other Packaging

Dimension

Logo Decals

Packaging Instructions and Decal Placement

DSI 9387-011

D2729-1

N/A

D2729-3

Dart Aerospace Ltd

1270 Aberdeen Street
Hawkesbury, ON, K6A 1K7
CANADA
TEL.: 1 613 632 3336 FAX: 1 613 632 4443

TOE RING HOLE REPAIR KIT

P/N: DSI 9387-011 CHG001

B/N: BXXXXXX

Revision: Draft

Date: 07.11.19

H:\Admin-q\isoforms\PPP-1.Rev.A

FD
07.11.19